

ID	Title	Location (exact)	Rating (current)
7215	Incomplete Interventional Radiology Pathway documents	Radiology	3
7016	Inadequate access to Interventional radiology for cancer patients, resulting in delayed diagnosis/treatment and poor experience	Radiology	4
7588	PET CT scanner MET contact via mobile telephone	Radiology	6
7690	MRI-2 water pressure	Radiology	6
7288	Risk of damage to DR detectors	Radiology	6
7302	Radiology is currently not able to meet the anticipated future CT/MRI demand	Radiology	6
7770	Risk of damage to DR detectors	Radiology	6
7771	Risk of lost or delayed PET/CT requests as a result of existing paper-based process	Radiology	6
7772	Sectra PACS running slowly	Radiology	6
7803	Unregistered staff requesting ionising radiation imaging tests	Radiology	6
7837	Spinal X-Ray room 2 beyond end of life	Radiology	6
7945	Shortage of MSK Sonographers	Radiology	6
7854	Reliance on UHS IT infrastructure to outsource scans to Axon Diagnostics	Radiology	8
7876	IRR17 non compliance	Radiology	8
7838	CT1 - recurrent failure	Radiology	8
7804	Medical Physics provision in Radiology	Radiology	8
7816	Insufficient Radiology Admin Workforce	Radiology	8

7290	Weekend MRI inpatient scanning	Radiology	8
7575	Referrer error wrong patient Radiation Incidents	Radiology	8
7513	No MRI Safety expert in post at SDH	Radiology	8
7514	Insufficient Radiology Reporting Capacity	Radiology	9
7727	Nuclear Medicine Gamma Camera beyond end of life	Radiology	9
7301	Lack of Uroradiology sub specialty skills amongst SDH Consultant body	Radiology	9
7289	Medical Physics provision in Radiology	Radiology	9
7510	Advanced Practitioner Radiographer (screening) single point of failure	Radiology	9
7511	Insufficient Radiographer X-Ray Reporting capacity	Radiology	9
7512	Lone-working Radiographer overnight - manual handling & security concern	Radiology	9
7835	No 24/7 access to MRI scanning	Radiology	9
7836	Power supply issues risk damaging CT scanners	Radiology	9
7839	Radiology reporting backlog	Radiology	9
7840	Frequent sewage leaks in Nuclear Medicine injecting room	Radiology	9
7778	Relocation of C-Arm X-Ray units between main theatres and DSU	Radiology	9
7741	Inadequate Ultrasound Staffing for Outpatient Services	Radiology	9
7750	CT2 console end of life and now unsupported	Radiology	9

7768	Compromised MRI safety (MRI-1) due to location of CT scanners	Radiology	9
7769	Staffing pressures in Radiology Screening/Fluoroscopy team	Radiology	9
7899	Lack of Uroradiology sub specialty skills amongst SDH Consultant body	Radiology	9
7943	Operational Issues regarding set up of the Community Diagnostic Centre	Radiology	9
7779	Duty Radiology Intensity	Radiology	10
7780	On Call Duty Radiology Intensity	Radiology	12
7743	No Ultrasound QA Testing Programme in place	Radiology	12
7740	Work Related Musculoskeletal Disorders for Sonographers	Radiology	12
7639	Generic IT logins for InHealth Radiographers (CDC scanners)	Radiology	12
7855	No future provision of CT lung biopsies	Radiology	12
7900	Consultant Radiologist- unfilled posts, Consultant shortages	Radiology	12
7902	Voice Recognition increasingly unreliable for Radiology Reporting	Radiology	12